

Dale Bickel

From: Dale Bickel
Sent: Wednesday, May 29, 2019 7:07 AM
To: GREGG.SKALL@WBD-US.COM
Subject: W297BX BSTA-20190528AAU granted 5/29 (corrected call sign on subject line)



Special Temporary Authority For a Radio Broadcast Station

Audio Division, Media Bureau

Date: May 29, 2019
File Number: BSTA-20190528AAU
Call Sign: W297BX (FX)
Facility ID Number: 141682

For the reasons provided in the application request, and as emergency facilities for primary station WNOO (AM) have restored that station to the air, Special Temporary Authority for FM translator W297BX IS GRANTED for operation of the translator station with the parameters specified in the STA request only. The licensee is responsible for addressing any complaints of interference that may arise.

This STA authority expires **November 25, 2019**.

In light of this STA grant, silent station STA request BLSTA-20190516AAI for W287BX is DISMISSED as no longer Necessary.

Authorized by: Dale Bickel dale.bickel@fcc.gov
Senior Electronics Engineer

A copy of this e-mail will be posted in the FCC's CDBS database under the file number above.
Please retain a copy of this authorization for your records.

Considerations:

Licensee must take all steps to ensure that workers and the public are not exposed to radiofrequency exposure in excess of the Commission's exposure limit.

This Special Temporary Authority does not supersede any non-FCC-regulated requirements applicable to the STA-authorized facility. The licensee remains solely and wholly responsible for maintaining compliance with such requirements.

Requests for extension of STA may be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.